


2019-02-05 M:\Federal\EPAPAC\110103.Lane PFIS 309GIS\WKS\GAP\A3_Sep LP Sed.mxd EA Dallas ischwertz



Notes:
1. Only one screening value could be located for PFAS in sediment. It was the TCEQ TRRP Tier 1_{TotSedComb} PCL for Perfluorooctanoic sulfonic acid (1-Octanesulfonic acid, heptadecafluoro-1-) at a screening level of .114 mg/kg (or 114 mg/g). None of the detections for this compound exceeded this screening criteria.
2. PFAS samples were collected from LSED-1 and LSED-9

Legend

- Phase I RI Sediment Sample Location
- Previous Sediment Sample Location
- Stream
- Stream Seasonal
- Approximate Site Boundary

Wetlands

- Freshwater Emergent Wetland
- Freshwater Forested /Shrub Wetland
- Freshwater Pond
- Lake
- Riverine

Imagery Source:
Texas Orthoimagery
Program 2015 0.5 Meter DOQQ,
Texas Strategic Mapping Program, 2015.



Lane Plating Works, Inc. Superfund Site
Dallas, Dallas County, Texas

Phase I RI PFAS detections in Sediment